

WSB-1Y Portable Fluorescent Whiteness Meter



Technical parameters

Model	station WSB – 1 y
Measurement range	0 ~ 199
Content of measurement	blue ray whiteness r457 fluorescent whiteness F
Light source	LED light source
Lighting conditions	comply with GB/T3978 regulation 45/0
Display	LCD display
Measuring the aperture	15 ϕ
Minimum	0.1
Measurement repeatability	0.2
Error of indication	\leq & plusmn; 1
Using the environment temperature (5 °C ~ 35 °C)	Humidity (& le; 85% RH)
Transportation and storage environment	temperature (20 °C to 50 °C); Humidity (& le; 90% RH)
Power supply	dc 1.5V \times 5 AA alkaline dry batteries
Ac 220V/50Hz/ dc7.5v / 0.2a power adapter	ac/dc dual purpose.
Configuration	portable aluminum alloy packing case