

WSB-1 Digital portable whiteness meter



Technical parameters:

Measurement range	0 ~ 199
Whiteness formula	blue light whiteness $WB=R457$
Light source	LED light source
Lighting conditions	comply with GB/T3978 regulation 45/0
Display	LCD display
Measuring the aperture	15 ϕ
Minimum	0.1
Measurement repeatability	0.2
Error of indication	$\leq \pm 1$
Using the environment temperature (5 °C ~ 35 °C)	Humidity (\leq 85% RH)
Transportation and storage environment	temperature (20 °C to 50 °C); Humidity (\leq 90% RH)
Power supply	dc 1.5V \times 5 AA alkaline dry batteries;
Configuration	portable aluminum alloy packing case